



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining


MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

November 26, 2007

Supervisor 

Mine Name: Snowflake
Operator Name: Harborlite Corp/World Minerals

Permit number: S/027/0100
Inspection Date: November 19, 2007
Time: 1:30 pm

Inspector(s): Lynn Kunzler, DOGM

Other Participants: none

Mine Status: Inactive/reclaimed

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection while in the area.

Inspection Summary:

Permit fees have been paid for this year. The operator has a reclamation surety for this site in the amount of \$18,600. The Milford Flat fire affected this site this summer. Most of the vegetation in the area was burned off. There has been no activity at this site. The regrading work has been completed and it appeared that the area had been composted and seeded. However, any vegetation that was established is gone (burned). The regrading work was good. There were no erosion problems noted on site.


The GPS was used to document the location of this site and the access route to the site.

Photos were taken to document site conditions.

Conclusions and Recommendations:

It is unlikely sufficient desirable vegetation will establish without additional seeding. If fire mitigation work does not reseed this area, then the operator may want to consider reseeding.

Continue to monitor the site when in the area.

Inspector's Signature 

LK:pb

cc: Jerry Mansfield, BLM

O:\M027-Millard\S0270100-Snowflake\inspections\Insp-11192007.doc